

Hardware & Other Materials	QC01, QC02, QC04, QC05, QC06, QC07, QC09, QC13, QC15, QC16, QC17, QC21, QC22, QC23, QC24, QC25, QC26, QC27, QC28
Raw Material	QC01, QC02, QC04, QC05, QC06, QC07, QC15, QC17, QC20, QC21, QC22, QC23, QC24, QC25, QC26, QC27
Special Processes (Heat Treat, Plating, Welding)	QC01, QC02, QC03, QC05, QC06, QC07, QC10, QC11, QC13, QC15, QC17, QC21, QC22, QC24, QC25, QC26, QC27
Calibration & Other Outside Services	QC01, QC02, QC05, QC06, QC07, QC08, QC09, QC10, QC12, QC13, QC14, QC15, QC16, QC17, QC19, QC21, QC22, QC24, QC25, QC26, QC27

QC01	Quality System	Supplier shall establish and maintain a Quality System acceptable to A & J Manufacturing, for the goods and/or services purchased under this purchase order. As a minimum, the supplier's Quality System must meet the requirements of ISO9001 or better
QC02	AS9100 Compliant	The supplier is required to maintain a Quality System in compliance to AS9100. If facility is not certified to AS9100, buyer reserves the right to conduct surveillance at supplier's facility to make final determination that Supplier's Quality System meets the requirements, and/or supplier will be required to complete a Supplier Survey Questionnaire.
QC03	NADCAP Approval	Special processing NADCAP approval is required. The special process requirements will be listed on the actual purchase order.
QC04	Supplier Furnished Material	Supplier shall submit Chemical and Physical test reports in accordance with the latest material specifications and revision. Distributors must provide a certification verifying the materials traceability to the Mill test reports when supplied.
QC05	Sub-Contractor Flow Down	Supplier is required to flow down the requirements of this purchase order, including terms and conditions to the Supplier's subcontractors. Flow down of key characteristics is required when specified on the face of purchase order.
QC06	Record Retention and Disposition	As a minimum, the Supplier is to retain records for at least 10 years from the date of shipment under each



9		applicable order for all products/part numbers unless otherwise specified in the order. In special circumstances, the purchase order will identify the actual required number of years that the records should be maintained. After the minimum retention period is achieved, suppliers may disposition the records as archive or destroy at their discretion.
QC07	Measuring & Test Equipment	The Supplier's equipment shall be calibrated in accordance with ANSI/NCLSL Z540-1 or ISO 10012-1 and traceable to NIST.
QC08	A & J Manufacturing Furnished Property	Supplier is to return all furnished property to A & J Manufacturing at the completion of the purchase order. Furnished property may include but not be limited to the following: drawings, mylars, process specification, tooling, fixtures, and excess raw material.
QC09	Parts Identification T	The Supplier is to identify parts in accordance with purchase order requirements.
QC10	Nonconformance Corrective Action	The Supplier is to notify A & J Manufacturing of any Nonconformance prior to shipping product and obtain approval for disposition of any nonconforming product. In addition, the Supplier will maintain a system of handling non-conformances and corrective actions.
QC11	Special Processing Approval	The Supplier is to perform a special process on this purchase order. Special processing may include one of the following processes: heat-treating, stress relieving or Nondestructive testing. A & J Manufacturing shall identify the specific process specification and the end user on the purchase order. The Supplier should maintain its special process approval with the end user. If the Supplier is not currently approved for the specified process, it is the Supplier's responsibility to notify A & J Manufacturing immediately.
QC12	Dimensional Inspection Report	The Supplier is to document an actual dimensional inspection report and submit it to A & J Manufacturing at the completion of the purchase order.
QC13	First Article Inspection	The Supplier to submit a First Article per AS9102 with this purchase order. It should identify all the process specifications and dimensional data.



		The calibration vendor shall be accredited to
		ISO17025. All measuring and test equipment shall be
QC14	Calibration Vendor	calibrated in accordance with
, , , , , , , , , , , , , , , , , , ,		ANSI/NCLSL Z540-1 or ISO 10012-1 and traceable to
		NIST.
		Supplier to package parts in a manner that will
		protect parts from any kind of damage. No metal-to-
QC15	Packaging Protection	metal contact is ever allowed. In special
		circumstances, the purchase order may specify the
		manner the parts are to be packaged.
0616	Part Number Serialization	All parts should have unique serial numbers assigned.
QC16		Supplier is to maintain tractability throughout the
		production stage.
		A certification is required, stating that all the
QC17	Certificate of Conformance	products or services meet the contractual or purchase
QCI	Certificate of Conformance	order requirements. The certificate must list the part
		number and all the applicable process specifications,
	The Boeing Company	including up to date revision levels. The Supplier shall maintain a special process approval
QC18	Approved Process	from The Boeing Company on this purchase order.
	rippioved i focess	This purchase order deals with the drawing that
	Key Characteristics Data Required	identifies key characteristics. Both the Supplier and A
QC19		& J Manufacturing should have established a control
		plan prior to the placement of this purchase order.
0000	DIN AMEDICA ACT	Items procured under this purchase order must be
QC20	BUY AMERICA ACT	compliant with DFAR 252.225-7000
		A & J Manufacturing, our customers, and/or any
		applicable regulatory authority reserve the right to
		access the supplier's applicable areas of all facilities, at
QC21	Right of Entry	any level of the supply chain, involved in the order and
QC21		to all applicable records. Reason for access may
		include inspection of the item on order, status of the
		item, or reviewing quality records pertaining to the
		purchase order in question.
		Vendors Personnel must be made aware of:
QC22	QMS Awareness	• their contribution to product or service conformity.
	and the second s	• their contribution to product safety.
		• the importance of ethical behavior.
QC23	Counterfeit Prevention	Vendor must have a process in place to detect and
200		prevent the use of counterfeit parts/materials.
0024	Control & Monitoring	Vendor must maintain a Quality Level 295% and an OTD level 295%. If levels drop below target, supplier
QC24	Requirements	will be notified an
	49	will be nothica an



QC25	Change Notification	Supplier is to notify A & J Manufacturing of changes in product and/or process, changes of suppliers, changes of manufacturing facility location and, where required, obtain organization approval.
QC26	Acceptance Authority Media	Media such as inspection stamps and electronic signatures used for product acceptance/inspection must be controlled and traceable to the personnel they are issued to.
QC27	Verification on Supplier's Premises	Verification of product on supplier premises by A & J Manufacturing or its customers, does not remove the obligation to provide conforming products and shall not be used as the organizations evidence of conformity.
QC28	Shelf-Life Materials	The supplier provides the manufacturing date, shelf life, and expiration date for all limited shelf-life items under this order. All items will have 75% or more of their shelf life remaining at the time of shipment to Milli part. All items are packaged, labeled and transported per their applicable regulatory requirements.